

May 18, 2009

• **TEST REPORT** •

**PN 84149**


**ARDL Engineering**

*Timing Belt Testing*

Prepared For:

Mr. Clark Sharar  
Daytona Rubber Company, Inc.  
27002 North 145<sup>th</sup> Avenue  
Surprise, AZ 85387

Prepared By: \_\_\_\_\_



David Houk  
Staff Engineer

Approved By: \_\_\_\_\_



Mark Centea  
Manager Engineering Group

**ISO 9001:2000**  
Registered

ISO 9001:2000 Registered  
Member of ACIL: The American Council of Independent Laboratories

**MEMBER**  
**ACIL**

Letters and reports are for the exclusive use of the clients to whom they are addressed and shall not be reproduced, except in full, without the written permission of Akron Rubber Development Laboratory, Inc. (ARDL). The information contained herein applies to the specific material, products or processes tested or evaluated. No warranty of any kind is herein construed or implied. The liability of ARDL, Inc. shall be limited to the amount of consideration paid for services.

[www.ardl.com](http://www.ardl.com)

2887 Gilchrist Rd. | Akron, Ohio 44305 | [answers@ardl.com](mailto:answers@ardl.com)  
Toll Free (800) 830-ARDL | Worldwide (330) 794-6600 | Fax (330) 794-6610

